



- Key to Fire Symbols
- Existing fire resisting construction 30 min.
  - Existing Evac chair
  - Existing wheelchair refuge zone
  - Existing call point - manual
  - Existing 6 litre P50 foam fire extinguisher
  - Existing exit sign - internally illuminated
  - Existing emergency lighting luminaire
  - Existing audible warning device
  - Existing visual warning device
  - Existing smoke detector
  - Existing heat detector
  - Existing pushbar door ironmongery
  - Fire resisting glazed element
  - Existing self closing automatic release
  - Existing fire action sign - general

DATE	REVISION
A 27.3.08	EVAC CHAIR REPOSITIONED, EMERGENCY LIGHTS & SMOKE DETECTORS AMENDED. BU LOGO UPDATED
B 8.1.14	T102a, T105 & T106 CHANGED TO 'MUSIC ROOM'
C 30.9.14	UPDATE FOLLOWING WORKS TO CREATE CHAPLAINCY TEA ROOM & T123. OFFICES ALLOCATED TO HR & UNIONS.
D 29.4.15	T117 CHANGED TO 'STUDENT WELLBEING'
E 26.9.16	EXTINGUISHER POSITIONS & TYPES UPDATED
F 1.10.18	UPDATE FOLLOWING EXTENSION OF PRAYER ROOM, RELOCATION OF TEA ROOM PLUS ASSOCIATED CHANGES TO ADJACENT ROOMS.
G 31.7.19	UPDATE FOLLOWING FM WORKS TO FORM T107g.
H 12.1.22	DOOR REMOVED & WINDOWS ADDED BETWEEN T110g/b.
J 3.3.22	T114 & T115 ROOM NUMBERS CORRECTED.
K 16.11.23	DOOR WIDTHS UPDATED TO TA120 ENTRANCE & MUSIC ROOMS CORRIDOR.
L 2.4.24	T133 & T135 UPDATED TO 'CONTEMPLATION'.

THIS FIRE SAFETY PLAN IS GENERALLY BASED ON INFORMATION PROVIDED BY BU'S FIRE SAFETY OFFICER. IT IS THE RESPONSIBILITY OF ALL USERS OF THIS PLAN TO CHECK THE INFORMATION PROVIDED TO CONFIRM THE EXACT POSITIONS OF THE FIRE SAFETY EQUIPMENT, CAVITY BARRIERS ETC.

## FIRST FLOOR FIRE PLAN

### TALBOT HOUSE

TH/FP/2L

SCALE 1:200 at A3  
10th FEBRUARY 2006

